

CONTRACTOR SAFETY HANDBOOK

Version No : ____1.1___

Issue Date : June 2007

Issued By: Environmental Health & Safety Unit, Estates Office



Table of Contents

1.0	Purpo	se and Scope	1
2.0	Applic	ability	1
3.0	3.1	General Duties Site Supervision Control of Egress and Access	1-3
4.0	Gener 4.1 4.2 4.3 4.4 4.5 4.6 4.7 4.8	al Requirements	3-7
5.0	Perso	nal Protective Equipment	7
6.0	6.1 6.2 6.3 6.4	Jse of Plant and Equipment Electric Arc Welding Gas Welding and Gas Cylinders Woodworking Machine Abrasive Wheels Electric Tools Handheld Tools Lifting Appliances and Lifting Gears	8-12
7.0	Use of	f Dangerous Goods/Harmful/Flammable Substances	12-13
8.0	Safe L	Jse of Electricity	13-14
9.0	Work a 9.1 9.2	at Height Scaffolds and Working Platforms Ladders	14-15
10.0	Work i	n Confined Space	15-16
11.0	Site R	isk Self-Inspection	16-17
12.0	Safety	Training and Records	17-18
13.0	Accide	ent and Emergency Case Reporting and Investigation	18
Appe Appe	endix 1 endix 2 endix 3 endix 4	: 承判商工程:工地風險自我檢查表 : Summary of Safety Training Records	



1.0 Purpose and Scope

The purpose and scope of this handbook is to minimize risks associated with the activities of contractors who perform work for Hong Kong Baptist University (HKBU). This handbook identifies safety related performance requirements for HKBU contractors and the criteria that shall be established to effectively evaluate contractor compliance with this Safety Handbook and other regulatory requirements.

2.0 Applicability

- 2.1 This Contractor Safety Handbook applies to all HKBU's contractors whenever they carry out repairs, construction, alterations, maintenance improvements/renovations, extensions and additions within HKBU's Campuses or buildings with total contract sum exceed HK\$10,000.
- 2.2 The minimum safety requirements are set out in this Safety Handbook. It must not be assumed that the contents of this Safety Handbook contains every safety and health aspects which may arise relating to the contractor's work.
- 2.3 This Safety Handbook acts as a supplement to the Conditions of Contract and does not take precedent over the Contract conditions. If there are conflicts between conditions or requirements in this Safety Handbook and the Conditions of Contract, the latter will prevail.

3.0 Responsibility

3.1 General Duties:

- 3.1.1 HKBU requires all contractors employed to take all reasonable measures to ensure the health and safety at work of all its employees/sub-contractors and will comply with the HKBU's health and safety requirements and all applicable laws and regulations.
- 3.1.2 Contractors must ensure their employees/sub-contractors to follow the health and safety instructions or practices given to them at site or in this Safety Handbook.
- 3.1.3 Ignorance of the safety and health standards, instructions and procedures, and inadvertence and complacency at work will not be accepted as an excuse for neglect of duty.

Version: 1.1 Date: June 2007 Page No.: 1 of 18



- 3.1.4 Contractors should indemnify, defend and hold HKBU harmless from any liability associated with the contractors' non-compliance with the HKBU's health and safety requirements and non-compliance with applicable laws and regulations.
- 3.1.5 Contractors should accept sole responsibility for any acts or omissions with respect to any health and safety risks, incidents or liabilities encountered by the contractors.
- 3.1.6 Contractors should accept, without appeal, termination of the contract if HKBU determines that the contractors have falsified any required health and safety information, or if HKBU determines that the contractors are significantly deficient in their health and safety performance or capabilities.
- 3.1.7 Contractors should provide, upon request from HKBU, copies of all health and safety procedures and practices, and health and safety training records for contractor employees.
- 3.1.8 Contractors must report to HKBU any job related fatalities, injuries resulting in permanent disabilities, or regulatory violations.
- 3.1.9 Contractors should ensure all workers must possess valid safety licences (e.g. Green Card, Electrical Licence, Confined Spaces Workers/Competent Persons Licence, etc) issued by the authorized organizations as per legal requirements, otherwise, they cannot carry out HKBU's contractual works.

3.2 Site Supervision:

- 3.2.1 The contractor must nominate a senior member of his site staff to act as a "site representative". He/she should maintain day to day communications in respect of the work with the project-in-charge of HKBU.
- 3.2.2 The contractor's site representative is also responsible for contact and coordination with their subcontractors. The site representative should ensure that their subcontractors are fully aware of the safety requirements. The site representative is responsible for ensuring that the subcontractor's work meets these requirements.

Version: 1.1 Date: June 2007 Page No.: 2 of 18



3.2.3 The contractor must provide full and adequate site supervision during the progress of the work and keep a site representative available at all times. The site representative should be able to receive and act promptly, on behalf of the contractor, on all safety and health instructions issued by the project-in-charge/Environmental Health & Safety Unit (EHSU) personnel of HKBU or any other authorized personnel, such as occupational safety officers of Labour Department.

3.3 Control of Egress and Access :

- 3.3.1 Before starting work in any parts of the Campus, the contractor's site representative is required to inform the project-in-charge of HKBU for obtaining permission.
- 3.3.2 Prior to the start of work every time, the site representative and workers should report to the Security Office where working permit shall be issued.
- 3.3.3 All contractor workers are required to wear working permits while working in the Campus for easy identification.
- 3.3.4 The site representative is required to report to the Security Office upon completion of work every time and return all working permits in clean and good conditions.

4.0 General Requirements

4.1 Site Layout:

- 4.1.1 Arrange suitable perimeter fencing or hoarding where appropriate.
- 4.1.2 Ensure good visibility and safe access and egress at site entrance.
- 4.1.3 Provide adequate warning signs at the entrance or other conspicuous locations to alert trespassers.
- 4.1.4 Provide area for loading and unloading, storage of materials, plant and machinery.
- 4.1.5 Provide emergency procedures and statutory notices at conspicuous locations where necessary.
- 4.1.6 Remove all rubbish, crates, surplus materials etc. from the site as soon as possible and on a regular basis during the progress of the works so as to maintain unhindered access to, escape from and easy inspection of all work.

Version: 1.1 Date: June 2007 Page No.: 3 of 18



- 4.1.7 Avoid obstruction of the entrance, passageways, lift lobbies, stairways and fire escape routes by the raw materials, tools, appliances and debris of the working process on any occasions.
- 4.1.8 Provide and ensure suitable and adequate first-aid facilities and fire-fighting equipment being available in a clearly identified and accessible site location during the working periods.

4.2 Site Roads and Site Traffic:

- 4.2.1 Site traffic routes should be clearly indicated and maintained as level as is consistent with safe travel and should be carefully planned taking account of such potential hazards as falsework as well as the movement of workers to and from different working positions. Where possible an one-way system should be implemented.
- 4.2.2 Erect notice boards/signage clearly in the conspicuous locations in order to draw the drivers' attention on areas of potential hazards.
- 4.2.3 When vehicles have to cross public roads, drivers are responsible for seeing that the wheels and tyres are cleaned of mud so that the public roads will not be contaminated and no skidding hazard is created by mud deposited on the roads near the entrances to the sites. They are also responsible for seeing that their load is secure and does not present a risk to other road users.
- 4.2.4 Protect workers from the risk of being struck by vehicles if they have to work on haul roads. Display suitable warnings where drivers can see them in good time; cone off the area; wear fluorescent or reflective clothing if necessary.
- 4.2.5 Provide passengers of suitable widths and steps or stairs of suitable construction for safe passage of persons and materials.
- 4.2.6 Properly maintain all floors, passageways, doorways, steps and stairs to ensure that they are free from any obstructions, protuding tripping and slipping hazards.
- 4.2.7 Provide and maintain an rigid hand-rail or other suitable handhold with intermediate barriers on every staircase to prevent people falling through the open side.

4.3 Ventilation, Temperature and Lighting:

- 4.3.1 Provide and maintain an efficient ventilation system at the point of origin of the dust or fume or other impurities to prevent it from polluting the air in the workroom.
- 4.3.2 Maintain a reasonable temperature in every workplace.

Version: 1.1 Date: June 2007 Page No.: 4 of 18



- 4.3.3 Provide and maintain suitable and sufficient lighting, either natural or artificial, in every part of the premises in which persons work or pass.
- 4.3.4 Provide suitable and sufficient lighting on hoarding or external fencing for public safety.
- 4.3.5 Ensure that windows and skyslight used for lighting are kept clean and free from obstruction.
- 4.3.6 Emergency lighting shall be provided to escape route and workplaces where needed.
- 4.3.7 Low voltage should be used for temporary lighting, particularly in confined and damp conditions.

4.4 Dust and Noise Generation:

- 4.4.1 Provide plastic sheets to cover floors, existing furniture and equipment for working process generates dust.
- 4.4.2 Provide dust proofed hoarding/screening to restrict dust from spreading to other functional and occupied areas.
- 4.4.3 Maintain the noise generate during the construction to a minimum.
- 4.4.4 The Contractor shall inform the project-in-charge prior to any noisy working processes.
- 4.4.5 All noise or dust generated works affecting adjacent areas should be carefully planed and scheduled to minimise interruption.

4.5 Construction Waste Management :

- 4.5.1 The contractor shall maintain a proper waste management system in order to minimise waste production including proper controlling of raw materials, waste reuse and recycling.
- 4.5.2 The contractor shall be responsible for disposing all construction waste to the designated government waste disposal facilities.
- 4.5.3 The contractor shall be liable for opening billing account prior to the disposal according to the requirements as outlined in Construction Waste Disposal Charging Scheme.
- 4.5.4 Waste transaction records shall be provided to the project-in-charge after each disposal of construction waste at the government waste disposal facilities.

Version: 1.1 Date: June 2007 Page No.: 5 of 18



4.6 Housekeeping:

- 4.6.1 Keep all passageways, staircases, landings, and the means of escape clear and unobstructed at all times.
- 4.6.2 Stack raw materials and finished products safely, clear of passageways and means of escape.
- 4.6.3 Do not leave tools on the floor, or in any location where they can be easily dislodged. Provide proper storage, such as tool boxes or containers for tools and equipment.
- 4.6.4 Do not obstruct lighting and ventilation, any electrical power point and fire fighting equipment.
- 4.6.5 The floors of workplaces should be kept clean, tidy and in a non-slippery condition.
- 4.6.6 Provide and maintain proper drainage system to prevent water ponding.
- 4.6.7 Protruding nails in timbers or walls should be removed or bent over so that they do not constitute a hazard to people.

4.7 Typhoon and Rainstorm Actions:

- 4.7.1 When the Typhoon Signal no. 8 or above / Rainstorm "Black" Warning Signal is issued, the Contractor shall inform his workers to suspend work in outdoor areas.
- 4.7.2 The Contractor shall report to the project-in-charge of HKBU on the appropriate protection measures taken before leaving the working site in order to protect his work and the public in such adverse weather.
- 4.7.3 Secure and fasten the works, scaffolding and loose materials.
- 4.7.4 Isolate all gaseous supplies and electrical circuits or tools immediately.
- 4.7.5 Inspect the secure site and protect against possible of water flooding.
- 4.7.6 Inspect and remove any blockages to permanent or temporary drainage outlets and channels.
- 4.7.7 Inspect the site and report to the project-in-charge of HKBU any damages after the typhoon or rainstorm for insurance purpose.
- 4.7.8 The stoppage of work due to Typhoon or Rainstorm shall not vitiate the Contractor's right, duties and liabilities in the Conditions of Contract.

Version: 1.1 Date: June 2007 Page No.: 6 of 18



4.8 Fire Prevention:

- 4.8.1 Only minimum quantity of combustible and flammable substance(s) which is required for the work should be used during the work process.
- 4.8.2 Articles should not be left at places which would cause obstructions to the fire service installations (e.g. fire extinguisher, hose reels).
- 4.8.3 Means of escape and fire exits should be kept clear and unobstructed at all times.
- 4.8.3 Fire doors leading to the protected corridor/staircase should be kept closed.
- 4.8.4 Smoking is not allowed in the working sites.
- 4.8.5 Water should not be used on electrical equipment fires. When possible de-energise electrical equipment before fire fighting.
- 4.8.6 Make certain you know your escape route and assemble point in case of fire.

5.0 Personal Protection Equipment

- 5.1 Consider the provision of personnel protective equipment only after all measures for removing or controlling safety or health hazards have been proved reasonably impracticable.
- 5.2 Ensure that sufficient personal protective equipment are provided and that they are readily available for every workers who may need to use them.
- 5.3 The personal protective equipment shall provide adequate protection and comfort for continuous use and shall conform to the international safety standards.
- 5.4 The contractors shall ensure that all workers make full, proper use and storage of the personal protective equipment provided.
- 5.5 Where personal protective equipment is provided, do not willfully and without reasonable cause remove personal protective equipment to endanger yourself or others.
- 5.6 All workers who have been issued personal protective equipment shall ensure their good condition and report immediately any damage to the contractor's site representative for replacement.

Version: 1.1 Date: June 2007 Page No.: 7 of 18



6.0 Safe Use of Plant and Equipment

6.1 Electric Arc Welding:

- 6.1.1 Contractor's site representative shall inform the project-in-charge of HKBU of the location of the temporary power connection and welding process and apply for a hot work permit.
- 6.1.2 Workers shall wear suitable personal protective equipment during electric arc welding, including eye and hand protection.
- 6.1.3 Ensure that welding machines having a maximum current output exceeding 30A single phase or half the maximum demand of an installation in any one phase is directly connected to the mains on a 3-phase supply.
- 6.1.4 Keep the workplace dry, secure, free from combustible materials and obstructions.
- 6.1.5 Ensure proper and adequate ventilation of workplace to remove poisonous fumes and gases that are given off during welding.
- 6.1.6 Take precautions against flying sparks and hot slag where welding is being done near flammable materials and check the area before leaving. Make available fire extinguishers near the welding area.
- 6.1.7 The workpiece should be effectively earthed and all equipment should be earthed and insulated.
- 6.1.8 Check and ensure all equipment and external connections being in good conditions prior to work.
- 6.1.9 Do not carry out welding outdoor during rainy days.

6.2 Gas Welding and Gas Cylinders :

- 6.2.1 Contractor shall make sure that all workers have completed an approved training course and possess valid licences, otherwise, they cannot carry out any gas welding work.
- 6.2.2 Contractor's site representative shall inform the project-in-charge of HKBU of the location of the gas welding and flame cutting processes and apply for a hot work permit.
- 6.2.3 Workers shall wear suitable personal protective equipment during gas welding, including eye and hand protection.
- 6.2.4 Keep the workplace dry, secure, free from combustible materials and obstructions.
- 6.2.5 Ensure proper and adequate ventilation of workplace to remove poisonous fumes and gases that are given off during welding.

Version: 1.1 Date: June 2007 Page No.: 8 of 18



- 6.2.6 Take precautions against flying sparks and hot slag where welding is being done near flammable materials and check the area before leaving. Make available fire extinguishers near the welding area.
- 6.2.7 Keep gas cylinders at upright position both in storage and when in use.
- 6.2.8 Do not store gas cylinders in excess of the "exempted quantities" as stipulated in the Dangerous Goods Ordinance. Store at any time one cylinder of acetylene and one cylinder of oxygen per job-site.
- 6.2.9 Keep the gas cylinders from source of heat, flammable materials, corrosive chemicals and fumes.
- 6.2.10 Ensure that appropriate type of pressure regulators and flash back arrestors are installed and maintained in sound condition.
- 6.2.11 Ensure that hose lines are in sound condition and secure to avoid damage.
- 6.2.12 Always lift gas cylinders by suitable means. Do not slide them along the ground or drop them from trucks.
- 6.2.13 Do not connect a hose longer than needed. Prevent hoses from becoming kinked or tangled.
- 6.2.14 Post out "No Smoking" sign in the welding area to alert site personnel.

6.3 Woodworking Machine:

- 6.3.1 Install suitable and effective crown guard, riving knife and emergency stop to circular saw. Weatherproof on/off switch shall be used if the machine is located outdoor.
- 6.3.2 Keep the circular saw blades sharp at all times, and properly adjust the riving knife and top guard. Use saw blade of suitable diameter and adjust it properly so that the saw teeth cut vertically downward.
- 6.3.3 Use a push stick to prevent the hand from coming into contact with the blade of a circular saw.
- 6.3.4 Provide fire extinguishers adjacent to the work location. Remove sawdust regularly to minimise fire hazard.
- 6.3.5 Never use a woodworking machine until the worker has been properly trained in its use.
- 6.3.6 Ensure that the working space around a machine is unobstructed and the floor is clean and not slippery.
- 6.3.7 Workers shall wear suitable personal protective equipment during operating woodworking machinery, including ear and face protection.

Version: 1.1 Date: June 2007 Page No.: 9 of 18



6.3.8 Post out "No Smoking" sign in the welding area to alert site personnel.

6.4 Abrasive Wheels:

- 6.4.1 All abrasive wheels shall be mounted by competent persons who have been appointed in writing by the contractor. They should be well trained and have the practical experience for the mounting job.
- 6.4.2 Only trained persons shall be allowed to use abrasive wheels and cutting discs and apply for a hot work permit prior to work.
- 6.4.3 Workers shall wear suitable personal protective equipment while operating abrasive wheels, including eye protection.
- 6.4.4 Abrasive wheels shall be clearly marked in Chinese and English the maximum permissible speed in rounds per minutes (rpm) by the manufacturer. Check that the operating speed of the spindle of a machine does not exceed the maximum permissible speed of the wheel.
- 6.4.5 Run a new or replacement abrasive wheel of at least 1 minute before use.
- 6.4.6 Adjust the work rest as close to the face of the wheel as possible, in any case not exceeding 3.2mm to the wheel.
- 6.4.7 Ensure that the guard is in position and properly adjusted.
- 6.4.8 Never use the side of an abrasive wheel for grinding.
- 6.4.9 Never use undue pressure on the abrasive wheel.
- 6.4.10 Ensure that the floor in the vicinity of a grinding machine is in a good condition, free from obstruction and not slippery.

6.5 Electric Tools:

- 6.5.1 All electrical work shall be performed by qualified electrician.
- 6.5.2 Use approved type weatherproof socket/adapter for extension of power cable.
- 6.5.3 Check for and avoid to use defective or damaged cables, plugs, sockets and damaged or worn tools.
- 6.5.4 Keep loose cables of the floor out of the way of other people as much as possible.
- 6.5.5 Never permit equipment or circuit to become overloaded. Use the correct fuse rating and cable size at all times.
- 6.5.6 Ensure that electrical tools are effectively earthed.
- 6.5.7 Do not withdraw a plug from a socket by pulling the cable.
- 6.5.8 Avoid standing on wet or dam ground when using electric tools.

Version: 1.1 Date: June 2007 Page No.: 10 of 18



6.6 Handheld Tools:

- 6.6.1 Select the correct weight, size and tool for the job.
- 6.6.2 Keep handheld tools clean, in good condition and store in a safe place when not in use.
- 6.6.3 Handle all sharp hand tools with care. Protect all sharp edges properly if not in use.
- 6.6.4 Keep cutting edges sharp for accurate working and to avoid the need for unnecessary pressure.
- 6.6.5 Use only properly insulated tools for work on or near electrical apparatus/source.
- 6.6.6 Check for and avoid to use defective or damaged handheld tools.
- 6.6.7 Keep tools off ladders or overhead locations.
- 6.6.8 Avoid awkward wrist angles while using tools such as pliers.

6.7 Lifting Appliances and Lifting Gears:

- 6.7.1 All lifting appliances and lifting gears shall be of good construction, made of strong and sound materials, free from defects and properly maintained.
- 6.7.2 Every lifting appliance shall be thoroughly inspected/examined by a competent examiner(CE) and/or competent person(CP) periodically as per the legal requirements (refer to the below "Test, Examination and Inspection Frequency" table). A copy of report form shall be given to the project-in-charge of HKBU.
- 6.7.3 The safe working load shall be clearly and legibly marked on a lifting appliance / lifting gear in English and Chinese. No lifting appliance / lifting gear shall be used for any load exceeding its safe working load.
- 6.7.4 Every part of a load to be raised or lowered by a lifting appliance / lifting gear shall be securely fixed, suspended or supported.
- 6.7.5 Every crane shall be fitted with an automatic safe load indicator.
- 6.7.6 Power-driven lifting appliance shall be operated by a person who has attained the age of 18 years and trained and competent to operate it.
- 6.7.7 A crane shall only be operated by a person who has attained the age of 18 years and holds a valid certificate issued by the Construction Industry Training Authority.

Version: 1.1 Date: June 2007 Page No.: 11 of 18



6.7.8 The below table is showing the test, examination and inspection frequency of lifting appliance and lifting gear.

Item	Testing & Examination	Testing	Examination	Inspection	Report Form	Action By
Lifting Appliance (other than a crane, crab or winch)	Before use	-	-	-	Form 4	CE
Crane, Crab or Winch	During the preceding 4 years before use	-	-	-	Form 3	CE
All Lifting Appliances	Before use after undergone substantial repair, re-erection, failure, overturning or collapse	-	-	-	Form 3 Form 4	CE
	-	-	At least once in the preceding 12 months	-	Form 5	CE
	-	-	-	Within the preceding 7 days	Form 1	СР
Crane	-	After erection, removal to a new location, adjustment of any component member	Before erection (for all of the devices used for the anchoring or ballasting)	-	Form 2	CE
Chains, ropes & lifting gear	Before use	-	In the preceding 6 months before use	-	Form 6 Form 7	CE

Note:

- (1) Lifting Appliance = a crab, winch, teagle, pulley block or gin wheel used for raising or lowering, and a crane, sheerlegs, excavator, pile driver, pile extractor, dragline, aerial ropeway, aerial cable-way transporter or overhead runway, and also any part of any such appliance.
- (2) Lifting Gear = a chain sling, rope sling, ring or similar gear, and a link, hook, plate clamp, shackle, swivel or eyebolt.

7.0 Use of Dangerous Goods/Harmful/Flammable Substances

7.1 All dangerous goods, harmful or flammable substances (such as paint, solvent or adhesive) shall be handled and stored in a safe manner and in accordance with statutory requirements.

Version : 1.1 Date : June 2007 Page No. : 12 of 18	j
--	---



- 7.2 Smoking and naked lights (including electric arcs and oxyacetylene or other flame used in welding or cutting metals) shall be strictly prohibited when handling dangerous/flammable substances.
- 7.3 All containers should be clearly labelled to indicate contents. Never use a wrongly labelled container for chemicals.
- 7.4 Adequate ventilation shall be provided and ensured for the operators and the removal of the sources of ignition.
- 7.5 Workers shall wear suitable personal protective equipment during using dangerous/harmful/flammable substance, including eye, respiratory and hand protection.
- 7.6 Fire extinguisher shall be installed and maintained properly nearby the working site.
- 7.7 Suitable warning signs shall be posted in the prominent location to alert workers and public about the work in progress.
- 7.8 Exercise great care in the storage and use of chemicals at all times because they may be explosive, poisonous, corrosive or combustible.
- 7.9 Chemicals shall not be stored in corridors, points of egress or near a source of ignition.

8.0 Safe Use of Electricity

- 8.1 Under the Code of Practice for electric work, the Contractor shall employ registered electrical workers for all permanent and temporary electrical installations.
- 8.2 If the Contractor requires temporary power for his works, the site representative shall inform the project-in-charge of HKBU for arrangement at least one week in advance of the working location, power consumption and type of electrical equipment to be connected.
- 8.3 All outgoing electric wiring shall be properly protected and supported. Never leave them lying on ground unprotected to avoid damage and tripping over.

Version: 1.1 Date: June 2007 Page No.: 13 of 18



- 8.4 Ensure that all connections including cables, plugs, connectors are of proper sizes/ratings, firmly wired up and the protective conductors are earthed.
- 8.5 Earth leakage circuit breakers should be installed to trip the supply when overloading of the circuit or earth leakage occurs.
- 8.6 The design of the circuits shall in every respect comply with the current Code of Practice for the Electricity (Wiring) Regulation.
- 8.7 Lockout-tagout system shall be used for isolation of electrical supply if applicable.
- 8.8 Check for and avoid to use defective or damaged cables, plugs, sockets and damaged or worn appliances.
- 8.9 If it is due to the working process where the live electrical items are unavoidably exposed, appropriate barrier shall be provided to guard against direct contact with the live parts. In addition, a warning sign shall be posted in the prominent location to alert the workers and public.

9.0 Work at Height

9.1 Scaffolds and Working Platform:

- 9.1.1 The contractor shall take adequate steps to prevent any person on the site from falling from a height of 2 metres or more. Adequate steps shall include the provision, use and maintenance of one or more of the following: (a) working platforms; (b) guard-rails, barriers, toe-boards and fences; (c) coverings for openings; and (d) gangways and runs.
- 9.1.2 All scaffolds shall be inspected by a competent person prior to being put into use for the first time, after erection or alternation, at bi-weekly interval and after exposure to adverse weather conditions.
- 9.1.3 The competent person shall report on the prescribed form (FORM 5) to the contractor that the scaffold, including its associated working platforms is safe for use.
- 9.1.4 Working platform shall be checked to ensure that the platform is of an appropriate structure (constructed with 900-1150mm high guard-rails, 450-600mm high intermediate guard-rails, at least 400mm width gangway, 200mm high toe board) and closely boarded with planks of adequate thickness and no patent defects.

Version: 1.1 Date: June 2007 Page No.: 14 of 18



- 9.1.5 In all the circumstances of the case, it is impracticable to provide such scaffolds and working platforms and the contractor shall provide suitable and adequate safety belts to the workers.
- 9.1.6 Safety belts shall be attached continuously to a suitable and secure anchorage and have suitable fittings.
- 9.1.7 All loose materials and handheld tools shall be stored at safe place to prevent any falling hazard.

9.2 Ladders:

- 9.2.1 Use ladders only for simple work of short duration. They should be use primarily as a means of access and not as a working platform.
- 9.2.2 Ladders shall be of good construction with no missing or defective rungs, of sound material and adequate strength for the purpose for which it is used and is properly maintained.
- 9.2.3 Always spare one hand to hold the ladder firmly. Never lean over or stretch out to reach the work.
- 9.2.4 Do not carry tools or materials in hand when climbing up or down the ladder.
- 9.2.5 Use non-metallic ladders for electrical work or when working near electrical conductors.
- 9.2.6 Wear safety harness with lanyard anchored properly when working on the ladder at height of 2m or more if the provision of working platform is not reasonably practicable.
- 9.2.7 Inspect the ladder for any defects before each use or regularly.

 Display warning label to the defective ladder.
- 9.2.8 Do not erect straight ladder at a base angle exceeding 75 degrees or a 4(rise): 1(base) ratio.
- 9.2.9 Secure a straight ladder at the top. When it is impracticable to do so, firmly secure the ladder at the base by some effective means or by any person.

10.0 Work in Confined Space

- 10.1 No one shall enter a confined space :
 - (a) until a competent person has carried out a risk assessment of the confined space and appropriate safety measures have been taken;
 - (b) unless he is a certified worker;
 - (c) without instruction or permission from the person-in-charge of HKBU of the work;
 - (d) unless it has been ventilated and ensure that ventilation continues until the work is finished.

Version: 1.1 Date: June 2007 Page No.: 15 of 18



- 10.2 Contractor shall make sure that the certified worker and competent person have completed an approved training course and possess valid confined space licences, otherwise, they cannot carry out any confined space work.
- 10.3 Prior to entering a confined space, the internal atmosphere must be tested for oxygen content and hazardous/combustible gases by using a multi-gas detector by a competent person. And continuous forced air ventilation should be provided while testing carried out periodically. A copy of the gas testing report shall be submitted to the project-in-charge of HKBU.
- 10.4 Contractor shall provide and keep readily available in a satisfactory condition a sufficient supply of approved breathing apparatus, resuscitator, safety harness and lifeline and an audio and visual alarm.
- 10.5 Worker shall wear an approved type of breathing apparatus, harness and lifeline when entering a confined space where toxic gas has been suspected.
- 10.6 Ensure effective means of communication between the workers inside the confined space and the standby person at the entrance.
- 10.7 Do not smoke or use a naked light in a confined space or near opening leading to it.

11.0 Site Risk Self-Inspection

- 11.1 The site risk self-inspection procedures apply to all HKBU's contractors whenever they carry out repairs, construction, alternations, maintenance improvements/renovations, extensions and additions within HKBU's Campuses or buildings for *more than a week*.
- 11.2 It is the responsibility of the contractor's site representative to carry out the site risk self-inspection by using the prescribed checklist (refer to Appendix 1) at weekly interval. But if there is any change in the work nature within the interval, the site representative shall perform a new site risk self-inspection for evaluating any potential hazard there.
- 11.3 This process is aimed to identify any hazardous conditions arising from existing site activities and take subsequent corrective action for preventing serious injury or other loss. And it can monitor the workers/sub-contractors in fulfilling the safety requirement throughout the working period.

Version: 1.1 Date: June 2007 Page No.: 16 of 18



- 11.4 For a non-conformance item identified during the site risk self-inspection, the site representative shall record the findings and follow-up actions in the inspection checklist properly.
- 11.5 The completed self-inspection checklist shall be reviewed and signed by the contractor's site representative.
- 11.6 An original copy of the self-inspection checklist shall be kept by the contractor while a copy of it shall be kept by the project-in-charge of HKBU.
- 11.7 The contractor's site representative shall be responsible to follow-up the corrective actions for any identified potential hazard and report the progress to the project-in-charge of HKBU promptly.
- 11.8 The project-in-charge shall verify whether the follow-up actions are completed or taken effectively to rectify the problems and record the results on the previous self-inspection checklist properly.

12.0 Safety Training and Records

- 12.1 All workers involved in HKBU's contractual works should possess adequate safety knowledge and awareness.
- 12.2 Contractors are required to provide such information, instruction, training and supervision as is necessary to ensure the safety and health at work of all workers/sub-contractors employed by him on sites.
- 12.3 Contractors are required to ensure that all workers/sub-contractors have attended and successfully completed mandatory general safety induction training course (i.e. Green Card) recognised by Labour Department.
- 12.4 For some specific work nature (e.g. confined space, welding and electrical work, etc), the contractor shall ensure that the worker has received the specific safety training and hold a valid licence as per legal safety requirements.
- 12.5 Contractors should keep all safety training records of workers/sub-contractors who will be working at HKBU's job site. And contractors shall make those records available for inspection upon the request of the project-in-charge of HKBU.

Version: 1.1 Date: June 2007 Page No.: 17 of 18



12.6 Prior to the commencement of work, contractor's site representative shall record the summary of the training records of all workers/sub-contractors working at HKBU's job site in the prescribed form (refer Appendix 3). And a copy of it shall be given to the project-in-charge of HKBU.

13.0 Accident and Emergency Case Reporting and Investigation

- 13.1 Contractor must verbally report dangerous occurrences (e.g. fire) and accidents involving death, serious injury or serious damage to the project-in-charge of HKBU immediately after the incident/accident.
- 13.2 Contractor shall investigate the incident/accident and must formally submit a written incident report in the prescribed form (refer to Appendix 4) within two working days of the dangerous occurrence or accident.
- 13.3 The contractor must provide the project-in-charge of HKBU with a photocopy of any Form 2 or other accident reports he submits to the Labour Department when requested by the project-in-charge of HKBU.

Version: 1.1 Date: June 2007 Page No.: 18 of 18

SITE RISK SELF-INSPECTION CHECKLIST

Date :			Time :		
Contractor's Nam	ne:				
P.O. No. :			Job Ref. No. :		
Worker's Name:	1	2	3	4	
Green Card No.:	1	2	3		
Construction Workers Registration Card No.:	1	2	3	4	
Inspected by :					
- ·	(Contractor's Si	te Representative)	-		

(This site risk self-inspection shall be conducted at weekly interval and if there is any change in work nature!)

1. Site Layout a. Sufficient hoarding erected to protect public? b. Maintain a safe access and egress at site entrance? c. Provide adequate lighting at work area? d. Post out suitable warning signs to alert trespassers? e. No projecting nail find in timber to endanger workers/public? f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
b. Maintain a safe access and egress at site entrance? c. Provide adequate lighting at work area? d. Post out suitable warning signs to alert trespassers? e. No projecting nail find in timber to endanger workers/public? f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
c. Provide adequate lighting at work area? d. Post out suitable warning signs to alert trespassers? e. No projecting nail find in timber to endanger workers/public? f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
d. Post out suitable warning signs to alert trespassers? e. No projecting nail find in timber to endanger workers/public? f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
e. No projecting nail find in timber to endanger workers/public? f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
f. Keep site tidy and material stacked safely? 2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
2. Personal Protective Equipment a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
a. All site personnel wear safety helmets? b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
b. Workers wear appropriate goggles whilst involving grinding, chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas	_	
chipping, cutting process? c. Workers wear ear protectors whilst working in noisy environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas		
environment? d. Workers wear safety belts whilst involving work at height (more than 2 metres) 3. Use of flammable substance/gas	_	
(more than 2 metres) 3. Use of flammable substance/gas	_	
	_	
a. Oxy-acetylene cylinders		
i. Maintain oxy-acetylene cylinders at upright position?	_	
ii. Install flash back arrestors, pressure regulators and single-valve hose at oxy- acetylene cylinder setup?	_	
iii. Install fire extinguisher nearby?	_	
iv. Cylinder hoses are free from defects/leakage?	_	
v. Maintain adequate ventilation?	_	
vi Workers wear appropriate Personal Protective Equipment?		
vii. Post out " No smoking " sign to alert site personnel?	_	

Item	Yes	No	N/A	Follow-up Actions
b. Paints/ solvent / chemical				
i. All containers properly labelled?				
ii. Post out warning signs to alert workers and public?				
iii. Install fire extinguisher nearby?				
iv. Wear appropriate Personal Protective Equipment?				
4. Electrical work				
a. Appointment of competent person to carry out the electrical work? (If yes, electric licence no.:)				
b. Use lockout-tagout system if applicable?				
c. Provide suitable earthing?				
d. Use waterproofed typed sockets, wires and connectors?				
e. Refer (b), they are in good condition?				
5. Wood-working machine				
a. Install crown guard to circular saw?				
b. Install riving knife?				
c. Install emergency stop?				
d. Install fire extinguisher?				
e. Post out " No smoking " sign to alert site personnel?				
f. Wear suitable Personal Protective Equipment?				
6. Hand Tools				
a. All hand tools are free from defects?				
b. All hand tools stored in safe place?				
c. Suitable hand tool used in particular process?				
d. Install suitable guarding to dangerous parts?				
e. Appointment of competent person to mount abrasive wheels?				
7. Work At Height (Above 2 metres high)				
a. Provide a working platform (constructed with 900-1150mm high guard-rails, 450-600mm high intermediate guard-rails, at least 400mm width gangway, 200mm high toe board)?				
b. If (a) is not available, provide safety belts to concerned workers and attaching to anchorage point?				
c. All loose material, hand tools are stored at safe place to prevent any falling hazard?				
8. Others				
	Ļ	<u> </u>	<u> </u>	

工地風險自我檢查表

日期:			時間:		
分判商名稱:_			工作類別:		
採購單編號:_			工作參考編號:		
工人姓名:	1	2	3	4	
平安咭編號:	1	2	3	4	
建造業工人 註冊証編號:	1	2	3	4	
檢查者姓名:		(分判商工地代表)	簽署:		
	'	のが削削上地下へかり			

(此工地風險自我檢查須於每星期或如工作性質有任何改變而進行一次!)

請在每條問題內右邊適當位置填上" X "。

項目	是	否	不適用	跟進事項
1. 工地環境				
a. 矗立圍板以保護公眾?				
b. 工地出入口保持安全及暢通?				
c. 工作地方提供了足夠照明?				
d. 張貼合適的警告標籤以提醒閑人勿進工地內?				
e. 木材沒有凸出可傷害工人或公眾的釘子?				
f. 工地保持整齊及物件擺放妥當?				
2. 個人防護裝備				
a. 所有工地人仕已佩戴安全帽?				
b. 當進行磨、削或切割工序時,工人已佩戴合適的護目鏡?				
c. 當在高噪音環境下工作時,工人已佩戴護耳罩?				
d. 當進行高空工作時(超過兩米高),工人已佩戴安全帶?				
3. 使用易燃物品/氣體				
a. 氧乙炔氣樽				
i. 保持氧乙炔樽直立地擺放?				
ii. 氧乙炔氣樽裝置已安裝防回火器、調壓器及單向閥喉管?				
iii.附近已設有滅火筒?				
iv. 氣樽喉管是完好無缺?				
v. 保持空氣流通?				
vi 工人已佩戴合適的個人防護裝備?				
vii.張貼『禁止吸煙』警告標籤以提醒工地人員?				

IJ	[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]	是	台	个適用	跟進事項
b	· 油漆 / 溶劑 / 化學物品				
i.	所有容器適當地張貼了標籤?				
ii	. 張貼了警告標籤以提醒工地人員及公眾人仕?				
ii	i.附近已設有滅火筒?				
i	v. 已佩戴合適的個人防護裝備?				
4	· 電力工作				
a	. 僱用了合資格人仕進行電力工作? (如是,電牌編號:)				
b	. 如適用,應使用鎖牌系統裝置?				
c	. 提供合適的接地?				
e	. 使用防水式的插座、電線及連接器?				
f.	跟據(b)項,所有鎖牌系統裝置狀況良好?				
5	. 木工機械				
a	. 安裝風車鋸護罩?				
b	. 安裝鋸尾刀?				
c	. 安裝急停掣?				
d	. 設有滅火筒?				
e	. 張貼『禁止吸煙』警告標籤以提醒工地人員?				
f.	已佩戴合適的個人防護裝備?				
6	. 手提工具				
a	. 所有手提工具沒有損壞?				
b	. 所有手提工具存放在安全地方?				
c	. 使用合適的手提工具進行指定工作?				
d	. 危險部份已安裝合適的防護罩?				
e	. 僱用合資格人仕安裝火石轆?				
7	. 高空工作 (超過兩米高)				
a	. 提供工作台(最高的護欄須 900-1150 毫米高、中間的護欄須 450-600 毫米高、路徑的闊度須至少 400 毫米闊、底護板的 高度須 200 毫米高)?				
b	. 如(a)項不適用,須提供安全帶給有關工人,並須保持將安全帶一直繫於穩固的繫穩物?				
С	所有鬆散的物件及手提工具須存放在安全的地方,以避免高空墮物?				
8	. 其他				
	·				

SUMMARY OF SAFETY TRAINING RECORDS 安全訓練記錄

Contractor's Name	Work Nature
分判商名稱 :	工作性質 :
P.O. No.	Job Ref. No.
採購單編號:	工作參考編號:
Prepared By	Date
塡寫者姓名:	_ 日期:

(Contractor's Site Representative)

Item 項目	Name 姓名	I.D. No. 身份証 編號	Green Card No. 平安咭編號 (Valid Date 有效日期)	Confined Space Licence No. 密閉空間証書編號 (Valid Date 有效日期)	Electric Work Licence No. 電牌編號 (Valid Date 有效日期)	Other Licence No. 其他証書編號 (Valid Date 有效日期)
1.						
2.						
3.						
4.						
5.						
6.						
7.						
8.						
9.						
10.						
11.						
12						
13.						
14.						
15.						

Appendix 4

HAZARDOUS OCCURRENCE INVESTIGATION REPORT

1.TYPE OF OCCURRENCE 發生種類 □ Explosion □ Loss of Consciousness □ Disabling 爆炸 失去知覺 受傷 □ Other	緊 急 措	rocedure 施 Depa	IS Unit File No. 竟健康及安全部門檔案號碼 artment File No. 檔案號碼				
3.Name of Faculty/Department and office location 院系/部門及辦事處地點			Telephone number 電話號碼				
Site of hazardous occurrence 肇事地點	Date and Time of hazar occurrence 日期 / 時間		ther Conditions 情況				
Witnesses見證人	姓名						
4.Description of what happened 事發因由 Brief description and estimated cost of property damage簡單描述及估計物業價值損失							
5.Name of Injured Person 受傷人姓名	Age 年歲	Occupation/Profession/Subject major 工作/專業/主修科目					
Description of injury 受傷描述	Sex 性別	Year of experience in occupation/Year Study 工作經驗/學習年份					
Direct cause of injury			E傷原因				
Was training in accident prevention given to injured empl hazardous occurrence? 在這工作任務是否有給予安全訓練 □ Yes □No	•	tasks perforn	ned at the time of the				
6. Direct causes of hazardous occurrence 發生危險之直接							
7. Corrective measures and date department will implement 部門將會完成修正措施和日期							
Reasons for not taking corrective measures 不依照修正措施之理由							
Supplementary preventive measures 補充預防措施							
8.Name of person investigating 調査人員姓名	Signature 簽名 Date 日期		Date 日期				
Title 職位	Telephone Number 電話號碼						

9.Safety & health committee's or representative's comments 安全及健康委員會或其代表人員評語					
Committee member's or representative's name	Signature 簽名	Date 日期			
委員會人員或其代表人員姓名					
Title 職位	Telephone number 電話號碼				